

KODA Exploration LLC (10720)

WHP Misty 2-7 Pad

(Location ID:477611)

2022 Post-Reclamation Update

Reclamation Timeline:

- 05/11/2022 – 05/17/2022 Recontoured Pad (See Exhibit A, B & C)
- 05/18/2022 – Drilled Seeded Pad, Seeding Attempt 1 of 2. (No Photos available)
- 06/13/2022 – Repaired pad perimeter ripping for Stormwater Control (No photos available)
- 06/20/2022 – Post-Seeding Inspection, grass seeds having difficulty germinating due to thick/hard shale crusted that formed after hailstorm. (Exhibit D & E)
- 06/25/2022 – Broke crust surface with harrow and re-seeded pad, Seeding attempt 2 of 2 (Exhibit F)
- 09/11/2022 – Mowed growth on pad (No photos available)



Exhibit A



5/11/2022 - 5/17/2022 WHP Misty 2-7 Recontouring Pad. Drill seeded pad on 5/18/22 (seeding attempt #1 of 2. no photos).

Exhibit B



5/16/2022 WHP Misty 2-7 Drill seeded pad on 5/18/22 (seeding attempt #1 of 2. no photos).

Exhibit C



6/20/2022 WHP Misty 2-7 Post seeding inspection (note grass seeds having difficulty germinating due to thick/hard shale crust formed after hail storm).

Exhibit D



6/20/2022 WHP Misty 2-7 Post seeding inspection (note grass seeds having difficulty germinating due to thick/hard shale crust formed after hail storm).

Exhibit E



6/25/2022 WHP Misty 2-7 Broke surface crust with harrow and reseeded pad again (seed attempt #2 of 2).

Exhibit F