

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403322477

Date Received:
02/15/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>.TEP</u>	<u>970-285-9377</u>	<u>COGCCInspectionReports@terraep.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 707800037
Inspection Date: 12/19/2022 FIR Submit Date: 12/20/2022 FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335068

Location Name: CLOUGH-66S94W Number: 15SWSW County: _____
Qtrqr: SWS Sec: 15 Twp: 6S Range: 94W Meridian: 6
W
Latitude: 39.521193 Longitude: -107.880069

FACILITY - API Number: 05-045-00 Facility ID: 335068

Facility Name: CLOUGH-66S94W Number: 15SWSW
Qtrqr: SWS Sec: 15 Twp: 6S Range: 94W Meridian: 6
W
Latitude: 39.521193 Longitude: -107.880069

CORRECTIVE ACTIONS:

1 CA# 166645

Corrective Action: Install or repair required BMPs in order to achieve stabilization on location Date: 01/31/2023

Response: CA COMPLETED Date of Completion: 01/31/2023

Operator Comment: Some ruts on pad are frozen and will need to be bladed / graded smooth when weather and temperatures allow. Several loads of crushed gravel have been added to pad surface and high traffic areas to stabilize soft spots on pad. Corrective action complete. See attached pics.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Some ruts on pad are frozen and will need to be bladed / graded smooth when weather and temperatures allow. Several loads of crushed gravel have been added to pad surface and high traffic areas to stabilize soft spots on pad. Corrective action complete. See attached pics.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP Environmental Lead

Date: 2/15/2023 4:49:22 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403322477	FIR RESOLUTION SUBMITTED
403322482	Photo showing fresh gravel on pad
403322483	Photo showing fresh gravel on pad

Total Attach: 3 Files