

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/21/2023

Submitted Date:

02/22/2023

Document Number:

702500900**FIELD INSPECTION FORM**

Loc ID 315170	Inspector Name: Burchett, Kirby	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>34720</u> Name of Operator: <u>GORDON ENGINEERING INC</u> Address: <u>PO BOX 3525</u> City: <u>GRAND JUNCTION</u> State: <u>CO</u> Zip: <u>81502</u>				Findings: 7 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us	
Katz, Aaron	(970) 765-6300	aaron.katz@state.co.us	
Gordon, John	(970) 245-1958	johngordon1gordon@yahoo.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
103788	PIT	AC	09/16/2022		-	FEDERAL 10-4 SEPARATOR	AC
230362	WELL	PR	10/01/2021	GW	103-08024	FEDERAL 10-4	PR

General Comment:

COGCC Inspection Report Summary

On Tuesday, 02/21/2023, Inspector Kirby Burchett, conducted a routine field inspection at Gordon Engineering INC on the Federal #10-4 well, Location #315170, in Rio Blanco County, Colorado.
 This location is within or in close proximity to CPW Black Bear/High Priority Habitat/NSO Habitat/Density Habitat Wildlife Management Areas.

Any Corrective Actions from previous Inspections are still applicable.

While there, I observed normal production operations. During this inspection the following compliance issues were observed:

1. Bradenhead inaccessible or visible.
2. No visible Stormwater BMPs

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator unit includes attached storage tank. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911 / (970) 618-0811	
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	PIT		
Comment:	Woven wire		
Corrective Action:		Date:	

Equipment:

Type: Horizontal Heated Separator	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 0		
Comment:	Bradenhead inaccessible or not visible.		
Corrective Action:	Install appropriate fittings to allow Bradenhead visual inspection.	Date:	03/06/2023

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	103788	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	AC
Facility ID:	230362	Type:	WELL	API Number:	103-08024	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Free flow								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
		Gravel				
		Culverts				
Compaction						
Ditches						
		Ditches				

Comment: Limited storm water inspection due to location being covered with snow. No evidence of active Stormwater BMPs. Location slopes toward creek with scattered vegetation.

Corrective Action: Provide proper BMPs to prevent sediment migration from location and lease road.

Date: 03/27/2023

Pits: ☐ NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 103788 Lat: 39.886953 Long: -108.725361

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Corrective Action

Date: _____

Fencing:

Fencing Type: Livestock Fencing Condition: Adequate

Comment: _____

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment: _____

Corrective Action

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
702500906	Inspection Photos	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6030605