

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403332246

Date Received:  
02/28/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10774

Name of Operator: SUMMIT OIL & GAS LLC

Address: PO BOX 983038

City: PARK CITY State: UT Zip: 84098

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Brent Dullack

303-653-4407

bd@s-companies.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696105740

Inspection Date: 02/10/2023

FIR Submit Date: 02/13/2023

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: SUMMIT OIL & GAS LLC

Company Number: 10774

Address: PO BOX 983038

City: PARK CITY State: UT Zip: 84098

LOCATION - Location ID: 465272

Location Name: Castor 7-59 Number: 12 County: \_\_\_\_\_

Qtrqr: SWSE Sec: 12 Twp: 7N Range: 59W Meridian: 6

Latitude: 40.583298 Longitude: -103.925119

FACILITY - API Number: 05-123-00 Facility ID: 465272

Facility Name: Castor 7-59 Number: 12

Qtrqr: SWSE Sec: 12 Twp: 7N Range: 59W Meridian: 6

Latitude: 40.583298 Longitude: -103.925119

CORRECTIVE ACTIONS:

1 CA# 167399

Corrective Action: Comply with Rule 606.

Date: 02/20/2023

Response: CA COMPLETED

Date of Completion: 02/16/2023

Operator  
Comment:

Trash picked up to comply with Rule 606. Please see attached picture.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**2** CA# 167400

Corrective Action: Comply with Rule 1002.c. Corrective action date is the date the location was observed out of compliance.

Date: 02/10/2023

Response: CA COMPLETED

Date of Completion: 02/10/2023

Operator Comment: Per inspection #697504771 and #697503871 and #697503330 the COGCC is requesting we add soil to the stockpile. After the snow melts and the ground thaws we will seed the stockpile.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**3** CA# 167401

Corrective Action: Immediately install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices.

Date: 02/15/2023

Response: CA COMPLETED

Date of Completion: 02/15/2023

Operator Comment: Please see attached pictures. The location has a ditch and berm surrounding it that includes multiple sediment catch basins and outfalls. The erosion shown in the inspection that is upstream of the stormwater BMP's have been filled in and Summit will do some additional seeding of the are after the ground thaws and the snow melts.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Please see attached pictures

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sam Bradley

Signed: \_\_\_\_\_

Title: Partner

Date: 2/28/2023 8:02:15 AM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403332275	Pictures
-----------	----------

Total Attach: 1 Files