



STATE OF COLORADO

OIL AND GAS CONSERVATION COMMISSION

DEPARTMENT OF NATURAL RESOURCES

SUITE 380 LOGAN TOWER BUILDING

1580 LOGAN STREET

DENVER, COLORADO 80203

(303) 894-2109 FAX

(303) 894-2100

DENNIS R. BICKNELL
Director

JOHN R. STOWELL
Deputy Director

PATRICIA C. BEAVER
Technical Secretary

ROY ROMER
Governor

January 2, 1991

Mr. Dale Walters
Whiting Petroleum Corp.
1229 East Douglas Road
Fort Collins, Colorado 80524

RE: NW Brandon Unit #2-I: NE NE Sec. 5-T19S-R45W
NW Brandon Unit #5-I: NE SE Sec. 5-T19S-R45W

Dear Sir:

On November 13, 1990 a site inspection was conducted on the NW Brandon Unit #2-I and #5-I injection wells. Although the wells were plugged on July 31, 1990, the locations still require restoration. This is to formally advise you that the NW Brandon Unit #2-I and #5-I locations are required to be fully restored and ready for final inspection by a COGCC inspector within sixty (60) days. If the work is not completed by March 3, 1991 a minimum fine of \$500.00 may be levied against you for non-compliance with COGCC Rule 319 (8). Please contact COGCC inspector Dave Shelton once the work has been completed and ready for inspection.

If you have any questions feel free to contact me.

Very truly yours,

Larry Robbins
Petroleum Engineer

LR/mc

cc: Files
(#0660B)