

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/02/2023

Submitted Date:

03/02/2023

Document Number:

702500947

**FIELD INSPECTION FORM**Loc ID 336391 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10775

Name of Operator: KT RESOURCES LLC

Address: 3381 WESTBROOK LANE

City: HIGHLANDS State: CO Zip: 80129

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

3 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us	
Gale, Tony	(303) 886-8733	tony@kt-res.com	
Boulger, Levin		levin@kt-res.com	
Adams, Karen	(303) 886-8733	adams@kt-res.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231796	WELL	SI	07/01/2017	CBM	103-09467	FEE M-31-2-96N	SI
270739	WELL	SI	05/01/2020	GW	103-10406	ANT HILL UNIT RBCWG 6-11D	SI

**General Comment:****COGCC Inspection Report Summary**

On Wednesday, 03/01/2023, Inspector Kirby Burchett, started to conduct a routine field inspection at KT Resources on the FEE-62N96W 31SWSW Location, Location #336391, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District including High Priority/NSO/Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

While there, I found both wells in state of Temporary Abandonment.

Both wells are overdue for Mechanical Integrity Test (MIT) MIT require 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well. Well can only be returned to SI status if it has produced (without mechanic intervention) within 2 years.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with COGCC rules.

**Inspected Facilities**Facility ID: 231796 Type: WELL API Number: 103-09467 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Last Production - June/2017Corrective Action: Perform successful mechanical integrity test. If a successful MIT cannot be performed within 30 day CA time the well must be plugged within 3 months.Date: 04/03/2023Facility ID: 270739 Type: WELL API Number: 103-10406 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Last Production - March/2020Corrective Action: Perform successful mechanical integrity test. If a successful MIT cannot be performed within 30 day CA time the well must be plugged within 3 months.Date: 04/03/2023