

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403327409

Date Received:

02/22/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10651

Name of Operator: VERDAD RESOURCES LLC

Address: 1125 17TH STREET SUITE 550

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Michael Cugnetti

Phone

720-845-6901

Email

mcugnetti@verdadresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696105695

Inspection Date: 01/24/2023

FIR Submit Date: 02/01/2023

FIR Status: _____

Inspected Operator Information:

Company Name: VERDAD RESOURCES LLC

Company Number: 10651

Address: 1125 17TH STREET SUITE 550

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 457136

Location Name: Rohn 9-60 Number: 14A County: _____

Qtrqr: NWSE Sec: 14 Twp: 9N Range: 60W Meridian: 6

Latitude: 40.748536 Longitude: -104.058703

FACILITY - API Number: 05-123- -00 Facility ID: 457136

Facility Name: Rohn 9-60 Number: 14A

Qtrqr: NWSE Sec: 14 Twp: 9N Range: 60W Meridian: 6

Latitude: 40.748536 Longitude: -104.058703

CORRECTIVE ACTIONS:

1 ☒ CA# 167251

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a. Free fluids must be removed by EOB 02/02/2023 and stained soil must be cleaned up by CA date.

Date: 03/02/2023

Response: CA COMPLETED

Date of Completion: 02/02/2023

Operator Comment: All spilled material and stained soil was cleaned up and properly disposed of. See attached corrective action photo documentation.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

2 ☒ CA# 167252

Corrective Action: Comply with Rule 606 and remove debris.

Date: 02/07/2023

Response: CA COMPLETED

Date of Completion: 02/02/2023

Operator Comment: All debris was removed from location. See attached corrective action photo documentation.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

3 ☒ CA# 167253

Corrective Action: Install sign to comply with Rule 605.c.

Date: 03/02/2023

Response: CA COMPLETED

Date of Completion: 02/09/2023

Operator Comment: Tanks labeled. Owner of equipment removed from location. Photo documentation of label not taken.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

4 ☒ CA# 167254

Corrective Action: Operator shall immediately ensure operations are safe and will properly install safety controls for the observed hole/boring/subsidence pursuant to Rule 602.c. Corrective action date is the date the location was observed out of compliance. Through communications with the inspectors Supervisor staff was made aware of the significance of this situation on 02/01/2023 and immediate notification was made to the Operator to install safety controls.

Date: 01/24/2023

Note: Called Mike Cugnettis (Operator) on 02/01/2023 for notification purposes to backfill the open excavation.

Response: CA COMPLETED

Date of Completion: 01/30/2023

Operator Comment: Hole was filled in. Issue was discussed with contractor and confirmed this will be filled in immediately or covered/protected in the future.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

5 ☒ CA# 167255

Corrective Action: Comply with Rule 606 and remove any unused equipment.

Date: 02/15/2023

Response: CA COMPLETED

Date of Completion: 02/09/2023

Operator Comment: All unused equipment was removed from location. See attachment for corrective action photo documentation.

COGCC Decision: Approved pending re-inspection

Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with

COGCC
Representative: COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Cugnetti

Signed:

Title: Director of EHS&R

Date: 2/22/2023 12:05:15 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403327409	FIR RESOLUTION SUBMITTED
403327499	Corrective Action Photo Documentation
403327500	Corrective Action Photo Documentation
403327502	Corrective Action Photo Documentation
403327511	Corrective Action Photo Documentation
403327512	Corrective Action Photo Documentation
403327513	Corrective Action Photo Documentation
403327514	Corrective Action Photo Documentation

Total Attach: 8 Files