

September 5, 1968

Carl A. Houy
602 Patterson Building
Denver, Colorado

Re: Well No. 2 "A" Blumenkamp
C SE $\frac{1}{4}$ SW $\frac{1}{4}$ Sec 17-3S-56W

Dear Carl:

Attached are copies of the completion and plugging reports concerning the above well in Big Beaver Field.

Jim McKee of our office inspected the site and found that a small amount of water, with some gas, was leaking from the well. There is an area about 20 feet square saturated with this water.

We would appreciate any help you can give us to remedy this situation.

Very truly yours,

OIL AND GAS CONSERVATION COMMISSION

Frank J. Piro, Deputy Director

FJP:eh

Enclosure