



00333529

STATE OF COLORADO
GAS CONSERVATION COMMISSION
DEPARTMENT OF NATURAL RESOURCES

SUBMIT ORIGINAL AND 1 COPY



FOR OFFICE USE ONLY			
ET	FE	UC	SE

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> COALBED METHANE <input type="checkbox"/> INJECTION WELL <input checked="" type="checkbox"/> OTHER P&A		5. FEDERAL/INDIAN OR STATE LEASE NO.
2. NAME OF OPERATOR Carl A. Houy		6. PERMIT NO.
3. ADDRESS OF OPERATOR 718 - 17th Street, Suite 540 CITY STATE ZIP CODE Denver, CO 80202		7. API NO. 05-121-05568
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface At proposed prod. zone		8. WELL NAME Blomenkamp
12. COUNTY Washington		9. WELL NUMBER 7
		10. FIELD OR WILDCAT Big Beaver
		11. QTR. QTR. SEC., T.R. AND MERIDIAN SW/SE 17-3S-56W

Check Appropriate Box To Indicate Nature of Notice, Report or Notification

13A. NOTICE OF INTENTION TO:

- ☒ PLUG AND ABANDON
☐ MULTIPLE COMPLETION
☐ COMMINGLE ZONES
☐ FRACTURE TREAT
☐ REPAIR WELL
☐ OTHER _____

13B. SUBSEQUENT REPORT OF:

- ☐ FINAL PLUG AND ABANDONMENT
 (SUBMIT 3RD PARTY CEMENT VERIFICATION AND JOB LOG)
☐ ABANDONED LOCATION (WELL NEVER DRILLED -
 SITE MUST BE RESTORED WITHIN 6 MONTHS)
☐ REPAIRED WELL
☐ OTHER _____

*Use Form 5 - Well Completion or Recompletion Report and Log
 for subsequent report of Multiple/Commingle Completions
 and Recompletions

13C. NOTIFICATION OF:

- ☐ SHUT-IN/TEMPORARILY ABANDONED
 (DATE _____)
 (REQUIRED EVERY 6 MONTHS)
☐ PRODUCTION RESUMED
 (DATE _____)
☐ LOCATION CHANGE (SUBMIT NEW PLAT)
☐ WELL NAME CHANGE
☐ OTHER _____

14. DESCRIBE PROPOSED OR COMPLETED OPERATIONS ON THIS FORM (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent)

15. DATE OF WORK Within 60 days

TD: 5140', PBD: 5081'

Surface casing: 9-5/8" 32#/ft. set at 96' KB with 65 sax regular cement
 Production casing: 5-1/2" 15.5 & 14# J-55 set at 5117' with 200 sax cement.
 Perforations: 5033-36'.
 Current status: SI

Propose to:

1. Lay down rods and tubing.
2. Put 300' of sand in hole to cover perforations.
3. Lay 10 sack cement plug on top of sand.
4. Cut off casing at approximately 4100' (top of Niobrara) and pull casing.
5. Put 20 sack plug at base of surface and 10 sack cement plug at top of surface.
6. Cut off below plow depth and restore surface after welding on plate.

RECEIVED

AUG 07 1991

COLO. OIL & GAS CONS. COMM.

16. I hereby certify that the foregoing is true and correct

SIGNED

TELEPHONE NO. 572-0672

NAME (PRINT)

V. W. McNab II

TITLE

Engineer

DATE

8-6-91

(This space for Federal or State office use)

APPROVED

TITLE

DATE

8-19-91

CONDITIONS OF APPROVAL, IF ANY: *