



99999999

# OIL & GAS CONSERVATION COMMISSION FIELD INSPECTION REPORT


☐ NOTICE OF UNSATISFACTORY INSPECTION

1120 Lincoln Street, Suite 801

Denver, CO 80203

(303)894-2100

☒ NOTICE OF SATISFACTORY INSPECTION

API No. 05-

(121 - 5533)

LEASE NAME:

Westfork Unit 2

LOCATION:

NEW 19-35-55W

OPERATOR:

H+R

DATE:

9-23-96

INSPECTOR:

Ed Binkley

Insp. Type:

CA

Insp. Status:

PA

PA: Y

N

Pass/Fail: P

F

Viol.: Y

N

NOV: Y

N

## INSPECTION ITEM

## COMMENTS

## INPUT

<b>Well ID Signs</b> (Rule 210)	Cement plugs installed	✓
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904)	40 5x @ 110', 20 5x @ 30'	✓
<b>Fences</b> (Rule 604.C.(3), 1003.A)	Witness cementing operation	
<b>Tank Battery Equipment</b> (Rule 604)	using bulk hopper wheel	
<b>Fire Walls/Berms/Dikes</b> (Rule 604)	1 1/2" coil tubing unit.	
<b>General Housekeeping</b> (Rule 603.G)		
<b>Spills (Oil/Water)</b> (Rule 908)		
<b>Bradenhead</b> (Rule 207)		
<b>Drilling Well/Workover</b> (Rule 315)		
<b>Surface Rehabilitation</b> (Rule 317)		
<b>Miscellaneous</b>	Andy Silva Jerry Musgrave	

## CORRECTIVE ACTION REQUIRED:

weld plate on cut off 4' below ground, back fill cellar and work pit. Rip compaction from location and reseed.

Date Corrective Action Required By:

4-23-97

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File Green - Operator Canary - Well Site



00325634