

**COLORADO OIL & GAS CONSERVATION COMMIS
FIELD INSPECTION REPORT**



<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION <input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION	<div style="border: 2px solid red; border-radius: 50%; width: 40px; height: 40px; margin: 0 auto; display: flex; align-items: center; justify-content: center; font-size: 24px; font-weight: bold; color: red;">C</div> 1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100				
API No. 05- 121 -5495	LEASE NAME: West Fork Unit				
LOCATION: 3555W D 19	OPERATOR: HDR Well Svcs.				
DATE: 9/25/05 @ Tank Battery	INSPECTOR: RLF				
Insp. Type: PR	Insp. Status: P/F	PA: Y N	Pass/Fail: P <input checked="" type="radio"/> F	Viol: <input checked="" type="radio"/> Y N	NOV: <input checked="" type="radio"/> Y N

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210)		
Pits (Reserve/Production) (Rule 902, 903, 904)	skimp pit - covered, no freeboard, repair cover, not production pit - inadequate freeboard, oil weeds!	
Fences (Rule 604.C.(3), 1003.A)		
Tank Battery Equipment (Rule 604)	Incorrect sign (say water v. Berry)	
Fire Walls/Berms/Dikes (Rule 604)	Berms around tanks inadequate, full of weeds.	
General Housekeeping (Rule 603.G)		
Spills (Oil/Water) (Rule 908)	only spill near skimp pit free oil ponded on ground.	
Bradenhead (Rule 207)		
Drilling Well/Workover (Rule 315)		
Surface Rehabilitation (Rule 317)		
Miscellaneous	Tank battery looks abandoned/idle. Remove oil from prod water pit	

CORRECTIVE ACTION REQUIRED: Remove water & oil, increase berms for freeboard on ~~prod~~ skimp & water pits. Clean up spilled oil from skimp pit overflow, Remove weeds. Rebuild berms around tanks. Post correct sign.
 Date Corrective Action Required By: October 2, 1995 Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.