

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403352408

Date Received:

03/22/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 81490

Name of Operator: ST CROIX OPERATING INC

Address: P O BOX 13799

City: DENVER State: CO Zip: 80201

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Melnychenko, Paul

(303) 489-9298

stcroixexp@aol.com

Peterson, Andy

970-203-4263

andy@petersonenergyoperating.com

Dornbos, Ryan

303-915-9074

ryan@petersonenergyoperating.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 708200022

Inspection Date: 03/03/2023

FIR Submit Date: 03/09/2023

FIR Status: _____

Inspected Operator Information:

Company Name: ST CROIX OPERATING INC

Company Number: 81490

Address: P O BOX 13799

City: DENVER State: CO Zip: 80201

LOCATION - Location ID: 474453

Location Name: ALICE SEEDORF Number: 1 County: _____

Qtrqr: NESW Sec: 22 Twp: 2N Range: 49W Meridian: 6

Latitude: 40.123560 Longitude: -102.843830

FACILITY - API Number: 05-121-00 Facility ID: 474453

Facility Name: ALICE SEEDORF Number: 1

Qtrqr: NESW Sec: 22 Twp: 2N Range: 49W Meridian: 6

Latitude: 40.123560 Longitude: -102.843830

CORRECTIVE ACTIONS:

1 CA# 167980

Corrective Action: Clean up stained soil Per Rule 1002.f(2)D.

Date: 03/15/2023

Response: CA COMPLETED

Date of Completion: 03/16/2023

Operator Comment: On 03/16/2023 the stained soil under the BOP accumulator trailer was cleaned up and disposed of and the trailer has been removed from the location.

COGCC Decision: _____

COGCC
Representative:

2 CA# 167981

Corrective Action: Comply with Rule 1002.f.(2) to install and maintain BMPs in accordance with good engineering practices. Corrective action date is the date the location was observed out of compliance as the location should be in compliance at all times. Operator shall continue to control and manage stormwater BMP until final reclamation is achieved pursuant to Rule 1004.

Date: 01/17/2023

Response: CA COMPLETED

Date of Completion: 03/16/2023

Operator
Comment:

On the 03/16/2023, the location was evaluated for maintenance of BMPs and all soil surrounding the location was waterlogged and the edges of location are still too wet and soft to compact. The additional disturbance that would be created attempting to compact would create un-necessary damage and would not result in additional control of the already immobilized soil due to the moisture content.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ryan Dornbos

Signed: _____

Title: Petroleum Engineer

Date: 3/22/2023 8:45:10 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

--	--

Total Attach: 0 Files