


# Storm Water Management and Erosion control

## Location Name: TEP ROCKY MOUNTAIN LLC MOBIL-66S95W /33NWSW

### Location #: 323833



**Location Overview: Location is located in a high priority habitat area and is approximately 470 yards from the Colorado River**  
**Section/Township/Range: 33 6S95W**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC MOBIL-66S95W /33NWSW**  
**Location #: 323833**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC MOBIL-66S95W /33NWSW**  
**Location #: 323833**



**Photo #9235 Location lacks stabilization.**



**Photo #9237 Location lacks stabilization.**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC MOBIL-66S95W /33NWSW**  
**Location #: 323833**

Network:Mar 13, 2023 at 12:43:45 PM M



**Photo #9233 Insufficient tracking BMP at entrance to location to minimize the transport of sediment.**

Network:Mar 13, 2023 at 12:48:50 PM M



**Photo #9234 Insufficient tracking BMP at entrance to location to minimize the transport of sediment.**

**Storm water Management and Erosion control**  
**Access Road/Assoc. Location Name: TEP ROCKY MOUNTAIN LLC MOBIL-66S95W /33NWSW**  
**Access Road/Assoc. Location #: 323833**



**Access Road overview: Access road is approximately 270 yards long and is located in a high priority habitat area.**  
**Section/Township/Range: 33 6S95W**

## Storm water Management and Erosion control

Access Road/Assoc. Location Name: TEP ROCKY MOUNTAIN LLC MOBIL-66S95W /33NWSW

Access Road/Assoc. Location #: 323833

Network:Mar 13, 2023 at 12:51:33 PM M



Photo #9245 Access road lacks stabilization.

Network:Mar 13, 2023 at 12:54:43 PM M



Photo #9246 Access road lacks stabilization.

## Storm water Management and Erosion control

Access Road/Assoc. Location Name: TEP ROCKY MOUNTAIN LLC MOBIL-66S95W /33NWSW

Access Road/Assoc. Location #: 323833



**Photo #9251** Insufficient tracking BMP at entrance to access road to minimize the transportation of sediment.



**Access road and location entrance.**