


Storm Water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT-66S96W /36SESW

Location # 334947



Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC BARRETT-66S96W /36SESW
Location # 334947



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC BARRETT-66S96W /36SESW
Location # 334947



Photo #9273 Sediment trap in need of maintenance



Photo #9274 Sediment trap in need of maintenance

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC BARRETT-66S96W /36SESW
Location # 334947



Photo #9267 Sediment trap and ditch degradation.



Photo #9281 Rill erosion into sediment trap.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC BARRETT-66S96W /36SESW
Location # 334947




Photo #9275 Berm degradation. Berm in need of maintenance. SW corner of location.

Storm water Management and Erosion control

Access Road/Assoc. Location Name:

Access Road/Assoc. Location #: 334947



Access Road overview: Access road is located in a 411 a. area.

Section/Township/Range: 36 6S96W