

Inspection Photos

3/24/2023

Operator: CHEVRON USA INC - 16700

Location #314697

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location #314697



Photo 1: Photos 1-7 provide examples showing BMPs to stabilize, as well as to minimize degradation, tracking and off-site sediment transport are missing or insufficient.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location #314697



Photo 2: See comments under photo 1. 6 foot measuring stick for reference.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location #314697



Photo 3: See comments under photo 1. 6 foot measuring stick for reference.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location #314697



Photo 4: See comments under photo 1. 6 foot measuring stick for reference.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location #314697



Photo 5: See comments under photo 1.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location #314697



Photo 6: See comments under photo 1. Photo right also shows BMPs to allow for proper stormwater discharge from access road are missing or insufficient.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location #314697



Photo 7: See comments under photo 1. Photo shows tracking/rutting and off-site sediment transport onto Highway 64 from the access road. Refer to inspections #696204791 and #696204758.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location #314697



Photo 8: Photos examples showing soils stockpiles that have been pushed beyond the perimeter of the working pad, therefore expanding the disturbance of the Location. Photos show BMPs to minimize erosion, degradation and sediment transport are missing or insufficient.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location #314697



Photo 9: Trash debris on Location.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location #314697



March 24, 2023



March 24, 2023

Photo 10: Photos 10 and 11 show tanks on Location. Photos also show all signage information per Rule 605.h have not been installed at tanks (e.g. Operator name, tank capacity, etc...)

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location #314697



Photo 11: See comments under photo 10.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location #314697



Photo 12: Photos show leak observed at pump equipment; equipment observed connected to “produced water/brine” tanks on Location; fluids observed discharging onto pad surface and impacting stormwater. Photo also shows BMPs to prevent or contain a spill at the tanks, such as secondary containment, are missing or insufficient.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location #314697



Photo 12.b: Continued from photo 12. Photo shows BMPs to prevent or contain a spill, such as secondary containment, are missing or insufficient at tanks on the Location. Arrow shows area of equipment observed leaking.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location #314697



March 24, 2023



March 24, 2023

Photo 13: Photos taken from the east end of the Location. Photo shows disassembled well equipment improperly stored on the perimeter of the Pad. Equipment appears to have slid down, collecting soils within; soils now potentially impacted due to improper storage of production equipment.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location #314697



March 24, 2023



March 24, 2023

Photo 14: Photo shows chemical containers improperly stored on the Location; container labels identify contents as "400 SDE SAE 15W-48". Containers missing BMPs to prevent or contain a spill, such as secondary containment; some containers observed stored on their side, and/or missing plug within lid to contain contents.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location #314697



Photo 15: See comments under photo 14.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location #314697



Photo 16: Photo shows porta-john unit stored on the west end of the Location; container currently stored on a small trailer; unable to observed BMPs to properly secure trailer/container to prevent a spill; no other BMPs to prevent or contain a spill observed.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location #314697



Photo 17: Photo shows equipment improperly stored on off-site of the designated working pad areas.