

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403359454

Date Received:

03/29/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 76840

Name of Operator: SCHNEIDER ENERGY SERVICES INC

Address: P O BOX 889

City: FORT MORGAN State: CO Zip: 80701

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

SCHNEIDER, JEFF

970-867-9437

jeff@schneiderenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 708200054

Inspection Date: 03/15/2023

FIR Submit Date: 03/17/2023

FIR Status: _____

Inspected Operator Information:

Company Name: SCHNEIDER ENERGY SERVICES INC

Company Number: 76840

Address: P O BOX 889

City: FORT MORGAN State: CO Zip: 80701

LOCATION - Location ID: 317498

Location Name: APRIL-67N60W Number: 14SWNW County: _____

Qtrqr: SWN Sec: 14 Twp: 7N Range: 60W Meridian: 6
W

Latitude: 40.577006 Longitude: -104.067221

FACILITY - API Number: 05-123- -00 Facility ID: 317498

Facility Name: APRIL-67N60W Number: 14SWNW

Qtrqr: SWN Sec: 14 Twp: 7N Range: 60W Meridian: 6
W

Latitude: 40.577006 Longitude: -104.067221

CORRECTIVE ACTIONS:

1 ☒ CA# 168266

Corrective Action: Immediately install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices. Any impacted/eroded areas will need to be properly stabilized and reclaimed in accordance with Rule 1004, including impacts observed on adjacent land. Corrective action date is the date the location was observed out of compliance, as the location should be in compliance at all times.

Date: 03/15/2023

Response: CA COMPLETED

Date of Completion: 03/26/2023

Stormwater BMPs and erosion control BMPs have been implemented at site. Waddles placed up stream of the armored sediment trap. Check dams installed at current working surface berm and ditch. Berm has been

Operator Comment: compacted by equipment and then walked and recompactd by personnel. All working and reclaimed areas scarified and seeded.

Please see attached photos.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jessica Donahue

Signed:

Title: Compliance Specialist

Date: 3/29/2023 12:01:55 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403359454	FIR RESOLUTION SUBMITTED
403359476	Photos

Total Attach: 2 Files