



LORADO OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT



<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801	
<input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION		Denver, CO 80203	
		(303)894-2100	
API No. 05- 121 - 5513		LEASE NAME: West Fork Unit #7	
LOCATION: S WNE 19-35-55W		OPERATOR: H+R Well Service	
DATE: 9-23-96		INSPECTOR: Ed Brinkley	
Insp. Type: CA	Insp. Status: PA	PA: Y <input checked="" type="checkbox"/> N <input type="checkbox"/>	Pass/Fail: P <input checked="" type="checkbox"/> F <input type="checkbox"/> Viol.: Y <input checked="" type="checkbox"/> N <input type="checkbox"/> NOV: Y <input checked="" type="checkbox"/> N <input type="checkbox"/>

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210) None	CIBP set by H+R wireline	✓
Pits (Reserve/Production) (Rule 902, 903, 904)	@ 4900'. Previously set ✓??	.
Fences (Rule 604.C.(3), 1003.A)	Check invoice with Form 4.	
Tank Battery Equipment (Rule 604)	Cutoff ± 3870', difficulty	
Fire Walls/Berms/Dikes (Rule 604)	with pulling pipe loose	
General Housekeeping (Rule 603.G)		
Spills (Oil/Water) (Rule 908)		
Bradenhead (Rule 207)		
Drilling Well/Workover (Rule 315)	G+G Well Service	
Surface Rehabilitation (Rule 317)		
Miscellaneous	Harlan Hodge Andy Silva	

CORRECTIVE ACTION REQUIRED: keep plugging permit with onsite crew during plugging operations. Remove cement and restore site	
Date Corrective Action Required By: 3-23-97	Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.