

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403363519

Date Received:
04/03/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10797

Name of Operator: DESERT EAGLE OPERATING LLC

Address: 17101 PRESTON RD SUITE 105

City: DALLAS State: TX Zip: 75248

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

MARSHALL WESLEY

wmarshall@prohelium.com

O'CALLAGHAN DEIDRE

docallaghan01@gmail.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 690203937

Inspection Date: 02/24/2023

FIR Submit Date: 02/28/2023

FIR Status: _____

Inspected Operator Information:

Company Name: DESERT EAGLE OPERATING LLC

Company Number: 10797

Address: 17101 PRESTON RD SUITE 105

City: DALLAS State: TX Zip: 75248

LOCATION - Location ID: 481116

Location Name: Red Rocks Number: 35-15 County: LAS ANIMAS

Qtrqtr: NWNE Sec: 35 Twp: 29S Range: 55W Meridian: 6

Latitude: 37.478380 Longitude: -103.543750

FACILITY - API Number: 05-071-

-00

Facility ID: 481333

Facility Name: Red Rocks Number: 35-15

Qtrqtr: NWNE Sec: 35 Twp: 29S Range: 55W Meridian: 6

Latitude: 37.478380 Longitude: -103.543750

CORRECTIVE ACTIONS:

1 CA# 167736

Corrective Action:

Date: _____

Response: CA COMPLETED

Date of Completion: 03/30/2023

Operator
Comment:

Soil was separated along trench as was practical for the soil compostion; topsoil was segregated on the west side of the flowline ditch while the remaining horizons were segregated on the east side. Very rocky soil was encountered that hindered further segregation based on noted changes in physical characteristics such as color, texture, density or consistency. Desert Eagle Operating will comply with all applicable criteria listed in COGCC

Rule 1003 for Interim Reclamation.

COGCC Decision: _____

COGCC
Representative: _____

2 CA# 167737

Corrective Action: Comply with 1002.c

Date: 03/30/2023

Response: CA COMPLETED

Date of Completion: 03/30/2023

Operator Comment: Soil has been decompacted and graded back to be utilized for reclamation along the flowline. Operator has contacted the CSU Las Animas County Extension office and has recieved additional planting information and a list of native grass seed suppliers for continued interim reclamation.

COGCC Decision: _____

COGCC
Representative: _____

3 CA# 167738

Corrective Action: Operator shall immediately abide by the reclamation rules to minimize surface disturbances per the 1002e rule.

Date: _____

Response: CA COMPLETED

Date of Completion: 03/30/2023

Operator Comment: Desert Eagle Operating is abiding by Rule 1002E, Surface Disturbance Minimization. To the greatest extent practicable, all vehicles used by the Desert Eagle Operating, contractors, and other parties associated with the well do not travel outside of the original access road boundary. Unavoidable impacts have been mitigated through grading and soil decompaction. Over 50 tons of rock brought to the surface has been removed from the location..

COGCC Decision: _____

COGCC
Representative: _____

4 CA# 167739

Corrective Action: Comply with Rule 1003 a. and 606. for waste and debris removal.

Date: 03/30/2023

Response: CA COMPLETED

Date of Completion: 03/30/2023

Operator Comment: All tree debris at the location and along the flowline disturbance has been removed. Unused pipe has been removed from the location.

COGCC Decision: _____

COGCC
Representative: _____

5 CA# 167740

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 03/02/2023

Response: CA COMPLETED

Date of Completion: 03/17/2023

Operator Comment: Required BMPs per Rule 1002.f.(2) C, installed at well location. Flowline disturbance graded to prevent soil or sediment runoff. .

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Desert Eagle Operating has taken required corrective action and will continue to employ Best Management Practices to reasonably minimize land disturbances and facilitate future reclamation. Access roads are maintained so as to reasonably control dust and minimize erosion, alteration of natural features, removal of surface materials, and degradation due to contamination. Signs have been corrected with current operator information and posted at the road and at the wellhead location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Wesley Marshall

Signed:

Title: Principal

Date: 4/3/2023 4:44:53 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403363602	Red Rocks 35-15 Road Sign
403363614	Red Rocks Tree Removal #1
403363619	Red Rocks ROW Tree Removal #2
403363623	Red Rocks Pipeline ROW Rock Removal
403363625	Red Rocks Pipeline ROW Grading
403363750	Red Rocks 35-15 Well Sign and Location

Total Attach: 6 Files