

# Storm Water Management and Erosion control

**Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /4NENE**

**Location #: 334569**




**Location Overview: Location is approximately 70 feet from the Colorado River**

**Section/Township/Range: 4 7S95W**

# Storm Water Management and Erosion control

**Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /4NENE**

**Location #: 334569**



**Location Overview: Location is Located in a 411 a. internal buffer zone**

**Section/Township/Range: 4 7S95W**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /4NENE**  
**Location #: 334569**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /4NENE**  
**Location #: 334569**



**Photo #9557 Location lacks stabilization.**



**Photo #9559 Location lacks stabilization.**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /4NENE**  
**Location #: 334569**



**Photo #9564 Location lacks stabilization.**



**Photo #9567 Location lacks stabilization.**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /4NENE**  
**Location #: 334569**



**Photo #9565 Insufficient tracking BMP at entrance to location.**