

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/10/2023

Submitted Date:

04/11/2023

Document Number:

690204077

**FIELD INSPECTION FORM**Loc ID 333348 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 66561

Name of Operator: OXY USA INC

Address: PO BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

3 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
NEWVILLE TONI		toni_newville@oxy.com	
Kosola, Jason		jason.kosola@state.co.us	
Waggoner, Kyle		kyle.waggoner@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
333348	LOCATION	AC			-	Sheep Mountain Unit - Drill Site 3 047683X	RI

**General Comment:**

On 3/20/2023, Ryan Costa conducted a location inspection at the Drill Site 3 compressor facility.  
See attached photos and additional details within this report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	TRASH		
Comment:	There was some trash observed to the north off location from the compressor facility.		
Corrective Action:	Comply with Rule 606.	Date:	04/18/2023

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
Comment:	There was a leak that occurred at the compressor which sprayed out to the northeast. There are stained soils on location at the east side of the compressor and to the northeast that drifted off the location. There was blackened soils and vegetation with a hydrocarbon odor.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. Report spill or release of E&P waste or produced fluids Remove free fluids and contact COGCC EPS staff per Rule 912.b.			Date: 04/12/2023

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
690204079	Inspection Photos	<a href="http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6078101">http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6078101</a>