

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/05/2023

Submitted Date:

04/05/2023

Document Number:

702501092

FIELD INSPECTION FORM

| | | | | |
|---|------------------------------------|---|-------------------|---|
| Loc ID 315321 | Inspector Name: Burchett, Kirby | On-Site Inspection <input type="checkbox"/> | 2A Doc Num: _____ | Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED |
| Operator Information: OGCC Operator Number: 16700 Name of Operator: CHEVRON USA INC Address: 760 HORIZON DRIVE STE 401 City: GRAND JUNCTION State: CO Zip: 81506 | | | | Findings: 6 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested |
| | | | | ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE |

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------------|----------------|-------------------------------|---------|
| Kellerby, Shaun | (970) 712-1248 | shaun.kellerby@state.co.us | |
| Patterson, Chris | | Chris.Patterson@scoutep.com | |
| Sanford, Anita | (970) 551-8313 | Anita.Sanford@scoutep.com | |
| Regulatory, Rangely | | RangelyRegulatory@scoutep.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 230629 | WELL | PR | 07/01/2020 | OW | 103-08297 | A.C. MCLAUGHLIN 71X | PR |

General Comment:**COGCC Inspection Report Summary**

On Wednesday, 04/05/2023, Inspector Kirby Burchett, conducted a routine field inspection at Chevron USA Inc. on the A.C. McLaughlin 71X, Location #315321, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority and Density Habitats.

Any Corrective Actions from previous Inspections are still applicable.

While there during normal production operations the following compliance issues were observed:

1. Stormwater BMP implementation and maintenance.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: [911 / \(970\) 675-3700](#)

Corrective Action: Date:

Overall Good: ☐

| | | | | | |
|----------------|------|--------|--|--|--|
| Spills: | | | | | |
| Type | Area | Volume | | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|---------------------------|--|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Submersible Pump | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | Accessible with valve. | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Chemical tank on plastic containment | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| | | | | |
|----------------------|------------------|-----------------------|------------|------------------|
| Inspected Facilities | | | | |
| Facility ID: 230629 | Type: WELL | API Number: 103-08297 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | Submersible pump | | | |
| Corrective Action: | | | | Date: |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Berms | | | | | | |
| | | Gravel | | | | |
| | | Ditches | | | | |
| | | Culverts | | | | |
| | | Compaction | | | | |
| Ditches | | | | | | |
| | | | | Material Handling And Spill Prevention | | |

Comment: Location and lease roads lack stabilization. Insufficient BMPs to control vehicle tracking.

Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation.

Oil and gas operators shall implement and maintain vehicle tracking Best Management Practices (BMPs) to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action: Provide proper BMPs to prevent sediment migration from location and lease road.

Date: 04/21/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403366418 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6073547 |
| 702501093 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6073538 |