

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/10/2023

Submitted Date:

04/12/2023

Document Number:

690204084

FIELD INSPECTION FORMLoc ID 324498 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 66561

Name of Operator: OXY USA INC

Address: PO BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
OXY		COGCCinspections@oxy.com	
NEWVILLE TONI		toni_newville@oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211806	WELL	PR	02/01/2022	CO2	055-06041	DIKE MOUNTAIN UNIT 4-13	RI

General Comment:

This is a follow up stormwater management inspection.
 Previous corrective action has not been completed.
 The wellsite location was not inspected due to wet conditions.
 See attached photos and additional details within this report.

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Only a portion of the access road was inspected. Grading was performed along a portion of the road however no BMP's were installed and there is erosion occurring. There is no diversion for stormwater which will flow down the entire portion of the road causing further erosion. Sediment is being deposited offsite at beginning of the road. BMP's need to be installed to prevent erosion. E.G. gravel, ditches, water bars, sediment traps, check dams, ect. Previous corrective action has not been completed.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 11/01/2022

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690204085	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6079652