

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/07/2023

Submitted Date:

04/08/2023

Document Number:

702501115

FIELD INSPECTION FORM

 Loc ID 315010 Inspector Name: Burchett, Kirby On-Site Inspection 2A Doc Num: _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 10779
 Name of Operator: SCOUT ENERGY MANAGEMENT LLC
 Address: 13800 MONTFORT DRIVE SUITE 100
 City: DALLAS State: TX Zip: 75240
Findings:

- 9 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Regulatory, Rangely		RangelyRegulatory@scoutep.com	
Sanford, Anita	(970) 551-8313	Anita.Sanford@scoutep.com	
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us	
Patterson, Chris		Chris.Patterson@scoutep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230089	WELL	PR	10/01/2020	OW	103-07748	FEDERAL 1	PR

General Comment:[COGCC Inspection Report Summary](#)

On Friday, 04/07/2023, Inspector Kirby Burchett, conducted a follow up field inspection at Scout Energy Management LLC on the Federal 1 well, Location #315010, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

FIRR #403348941 and FIRR #403359777 in response to Corrective Actions on Field Inspection #702500992 from 3/9/23 have been corrected.

While there during normal production operations the following compliance issues were observed:

1. Stormwater BMP implementation and maintenance.
2. Signage at entrance to location pushed over.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with COGCC rules.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	Chemical tank labeling has been installed		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Operator information on well sign has been updated		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911 / (970) 675-3700	
Corrective Action:		Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Entrance to location signage pushed over and partially buried		
Corrective Action:	All trash, rubbish, and other waste material will be properly contained until removed from the Oil and Gas Location. At no time will trash, debris, or rubbish be placed or remain on the ground.		Date: <u>04/17/2023</u>

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank on plastic containment stand		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Accessible. Gauge installed.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 230089 Type: WELL API Number: 103-07748 Status: PR Insp. Status: PR

Producing Well

Comment: [Rod pump.](#)
[Last Production - June 2022.](#)
[Last Production Report - February 2023.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Gravel						
Berms						
		Culverts				
				Material Handling And Spill Prevention		

Comment: Lease road lacks stabilization. Insufficient BMPs to control vehicle tracking.
 Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation.
 Oil and gas operators shall implement and maintain vehicle tracking Best Management Practices (BMPs) to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action: Provide proper BMPs to prevent sediment migration from location and lease road.

Date: 04/24/2023

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403368523	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6075937
702501116	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6075934