

# Weld OEM Spill Report Form



Submission date: 15 April 2023, 10:16AM  
Receipt number: 974  
Related form version: 17

## Company

|              |                         |
|--------------|-------------------------|
| Company name | KP Kauffman and Company |
| Address      | 1700 Lincoln St., #4550 |
| City         | Denver                  |
| State        | Colorado                |
| Zip code     | 80203                   |

## Contact Information

|                |               |
|----------------|---------------|
| Contact person | Craig Meis    |
| Contact phone  | 303-825-4822  |
| Contact email  | cmeis@kpk.com |

## About the Spill

|                                       |                   |
|---------------------------------------|-------------------|
| Date incident occurred                | 04/13/2023        |
| How long did the spill/ release occur | Less than an hour |
| Was 9-1-1 called for this incident    | No                |
| Longitude                             | -104.88951        |

|                               |                               |
|-------------------------------|-------------------------------|
| Latitude                      | 40.01499                      |
| Fire department/district      | Greater Brighton Fire         |
| Where did the incident occur? | Oil and gas facility/pipeline |

## Oil and Gas Incident

|                              |                               |
|------------------------------|-------------------------------|
| Well site name               | David Howard Flowline Release |
| Section                      | 28                            |
| Township                     | 1N                            |
| Range                        | 67W                           |
| Where did the spill occur    | Pipeline                      |
| Have you submitted a form 19 | No                            |

## Product Spilled

|   |                          |
|---|--------------------------|
| Product spilled   | Crude Oil/Produced Water |
| Number of barrels spilled   | 1                        |
| Emergency precautions taken   | N/A                      |
| Extremely hazardous substance   | No                       |
| Acute or chronic health risks   | No                       |
| Did the spill affect or end near a waterway, irrigation ditch, or a retention pond? | No                       |
| What caused the spill/release?  | Corrosion                |

## Narrative

Include specific incident information and mitigation actions taken to stop and clean-up the spill/release

David Howard (Landowner) notified KPK of potential flowline release the evening of Thursday 4/13/23. KPK responded and confirmed it was part of the Facility 7 consolidated flowline and isolated the flowline segment and secured the site. Surface clean up began Friday morning 4/14 but due to weather and site conditions, clean up was limited to surface and site secured till conditions are better to excavate impacted soil and repair flowline.

Upload documentation collected

[Site Location Map Figure.pdf](#)  
[Photolog 041423.pdf](#)

Acknowledgement

I acknowledge that a written follow-up notice must be submitted to Weld County OEM/LEPC as soon as practicable after the release. The follow-up notice must update information included in the initial notice and provide information on actual response actions taken and advice regarding medical attention necessary for citizens exposed.