

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/10/2023

Submitted Date:

04/12/2023

Document Number:

690204084

**FIELD INSPECTION FORM**

Loc ID 324498 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 66561  
Name of Operator: OXY USA INC  
Address: PO BOX 173779  
City: DENVER State: CO Zip: 80217-

**Findings:**

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
NEVVILLE TONI		toni_newville@oxy.com	
OXY		COGCCinspections@oxy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211806	WELL	PR	02/01/2022	CO2	055-06041	DIKE MOUNTAIN UNIT 4-13	RI

**General Comment:**

This is a follow up stormwater management inspection.  
Previous corrective action has not been completed.  
The wellsite location was not inspected due to wet conditions.  
See attached photos and additional details within this report.

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Only a portion of the access road was inspected. Grading was performed along a portion of the road however no BMP's were installed and there is erosion occurring. There is no diversion for stormwater which will flow down the entire portion of the road causing further erosion. Sediment is being deposited offsite at beginning of the road. BMP's need to be installed to prevent erosion. E.G. gravel, ditches, water bars, sediment traps, check dams, ect. Previous corrective action has not been completed.

Corrective Action: **Install or repair required BMPs per Rule 1002.f.(2)C**

Date: 11/01/2022

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403371569	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6079657">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6079657</a>
690204085	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6079652">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6079652</a>