

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/21/2023

Submitted Date:

04/21/2023

Document Number:

708300329

FIELD INSPECTION FORMLoc ID 335297 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

21 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, CAERUS		COGCC.inspections@caerus oilandgas.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259587	WELL	PR	03/21/2001	GW	045-07757	PUCKETT 12-31D	PR
259588	WELL	PR	03/21/2001	GW	045-07758	PUCKETT 22-31D	PR
259589	WELL	PR	01/31/2002	GW	045-07759	PUCKETT 21-31D	PR
259590	WELL	PR	06/01/2021	GW	045-07760	PUCKETT 13-31D	PR

General Comment:**COGCC Inspection Report Summary**

On 4/21/2023 at approximately 09:50, Compliance Inspector Matthew Morris conducted an on-site inspection at CAERUS PICEANCE LLC, PUCKETT-66S96W/31SEW at Location ID #335297 in Garfield County, Colorado.

Normal production operations were observed.

During the inspection, the following compliance issues were observed:

- 1) Storage of unused supplies/equipment
- 2) Stormwater; refer to Stormwater section

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, and/or Wildlife Management area.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/(970) 285-2615

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Loading hose stored on ground next to tank battery		
Corrective Action:	Remove hose from location to comply with Rule 606	Date:	05/06/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Barbed wire fencing		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Pipe rail fencing		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbed wire fencing		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 4		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Centralized containment			
Corrective Action:				
Date:				

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						
Date:						

Paint

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Centralized containment				
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	259587	Type:	WELL	API Number:	045-07757	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	259588	Type:	WELL	API Number:	045-07758	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	259589	Type:	WELL	API Number:	045-07759	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	259590	Type:	WELL	API Number:	045-07760	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Compaction						
		Compaction				
Rip Rap						
Gravel						
Ditches						
Other	Fail					Inadequate vehicle tracking BMPs
		Other	Fail			Inadequate vehicle tracking BMPs
		Gravel				
Culverts						
Berms						
Other	Fail					Cut slope erosion running onto location
				Material Handling And Spill Prevention		Chemical tank in containment
Other	Fail					Site degradation from plow
		Culverts				

Comment: 1) Site degradation from plow causing transport of sediment and lack of stabilization
 2) Inadequate erosion BMP of cut slope causing run-on of sediment
 3) Inadequate vehicle tracking BMP to minimize transportation of sediment from location and access road

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to comply with Rule 1002

Date: 05/06/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708300331	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6090441