

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/06/2023

Submitted Date:

04/18/2023

Document Number:

700901419

FIELD INSPECTION FORMLoc ID 319634 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10330

Name of Operator: INVESTMENT EQUIPMENT LLC

Address: PMB 412 558 CASTLE PINES PKWY

City: CASTLE PINES State: CO Zip: 80108

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Bongers, Brent		bbongers@impetroresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
200276	WELL	PR	11/01/2022	OW	001-05299	CLIFFORD CAUSEY 17	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Bradenhead

1

Comment:

Corrective Action:

Date:

Type: Pump Jack

1

Comment: Rule 906: Stained soil around.

Corrective Action: Control and contain spills/releases and clean up per Rule 906. Corrective Action Date 5/19/2023 to remove stained soil. See attached photo #2.

Date: 05/19/2023

Type: Deadman # & Marked

4

Comment:

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 200276 Type: WELL API Number: 001-05299 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 12/23/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: Appeared to be plumbed to surface

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday April 6th. 2023, at approximately 12:45pm. I, Inspector Chane Finkenbinder, conducted an on-site inspection.</p> <p>Operator: INVESTMENT EQUIPMENT</p> <p>Location name: CLIFFORD CAUSEY # 17</p> <p>API # 001-05299</p> <p>Location ID #: 319634</p> <p>County: Adams</p> <p>While there, I observed a (Producing) well.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Rule 906: Stained soil around. Control and contain spills/releases and clean up per Rule 906. Corrective Action Date 5/19/2023 to remove stained soil. See attached photo #2.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	finkenbc	04/18/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403376958	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6085633
700901420	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6085627