

Stormwater Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO-66S95W /34SWSE

Location #: 334989




Location Overview: Location approximately 135 yards from the Colorado River.

Section/Township/Range: 34 6S95W

Stormwater Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO-66S95W /34SWSE

Location #: 334989



Location Overview: Location is located in a 411 a. internal buffer zone.

Section/Township/Range: 34 6S95W



Stormwater Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO-66S95W /34SWSE

Location #: 334989




Photo #9726 Location lacks stabilization.



Photo #9730 Location lacks stabilization.

Stormwater Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO-66S95W /34SWSE

Location #: 334989



Photo #9731 Location lacks stabilization.



Photo #9732 Location lacks stabilization.

Stormwater Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO-66S95W /34SWSE

Location #: 334989



Photo #9732 Location lacks stabilization.



Photo #9735 Insufficient tracking BMP to minimize the transport of sediment.