

TEP ROCKY MOUNTAIN LLC, Reppo/B Pad

Location # 334431



Location Entrance – Photo #02694

Location – Photo #02696

TEP ROCKY MOUNTAIN LLC, Reppo/B Pad

Location # 334431



Wellheads – Photo #02697



Separators – Photo #02695

TEP ROCKY MOUNTAIN LLC, Reppo/B Pad

Location # 334431



Tank Battery – Photo #02700



Weeds in Tank Berm – Photo #02701

TEP ROCKY MOUNTAIN LLC, Reppo/B Pad

Location # 334431



Open-Ended Load Line – Photo #02702



Location Lacks Stabilization – Photo #02698

TEP ROCKY MOUNTAIN LLC, Reppo/B Pad

Location # 334431



Location Lacks Stabilization – Photo #02705



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #02708