

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/25/2023

Submitted Date:

04/25/2023

Document Number:

702501190**FIELD INSPECTION FORM**Loc ID 314489 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Regulatory, Rangely		RangelyRegulatory@scoutep.com	
Patterson, Chris		Chris.Patterson@scoutep.com	
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us	
Sanford, Anita	(970) 551-8313	Anita.Sanford@scoutep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228830	WELL	PR	08/01/2022	OW	103-05817	MCLAUGHLIN A C 35	PR

General Comment:**COGCC Inspection Report Summary**

On Tuesday, 4/25/2023, Inspector Kirby Burchett, conducted a follow up field inspection at Scout Energy Partners on the McLaughlin A C 35 well, Location #314489, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority and Density Habitats.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection is in response to FIRR #403376459 for Corrective Action from Inspection #702501074 on 4/5/23.

While there during normal production operations the following compliance issues were observed:

1. Blading of location and access road did not correct needed Stormwater BMPs to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.
Refer to attached photographs for Corrective Action.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: [911 / \(970\) 675-3700](#)Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Submersible Pump	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank on containment		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Accessible with valve. Gauge installed. Hooked up to flowline.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 228830	Type: WELL	API Number: 103-05817	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Submersible pump			
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
				Material Handling And Spill Prevention		
Berms						
		Ditches				

Comment: [Insufficient Stormwater BMPs to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.](#)

Corrective Action: [Provide proper BMPs to prevent sediment migration from location and lease road.](#)

Date: 05/25/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403384303	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6093513
702501191	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6093510