

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403391959

Date Received:
05/03/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10690

Name of Operator: IMPETRO RESOURCES LLC

Address: 558 CASTLE PINES PKWY UNIT B-4

City: CASTLE PINES State: CO Zip: 80108

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Bongers, Brent

3619355633

bbongers@impetroresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 708200185

Inspection Date: 04/20/2023

FIR Submit Date: 04/27/2023

FIR Status: _____

Inspected Operator Information:

Company Name: IMPETRO RESOURCES LLC

Company Number: 10690

Address: 558 CASTLE PINES PKWY UNIT B-4

City: CASTLE PINES State: CO Zip: 80108

LOCATION - Location ID: 317363

Location Name: CHRISTIANSON-SWD-63S50W Number: 12SWNW County: _____

Qtrqr: SWN Sec: 12 Twp: 3S Range: 50W Meridian: 6

Latitude: 39.810680 Longitude: -102.930559

FACILITY - API Number: 05-121- -00 Facility ID: 317363

Facility Name: CHRISTIANSON-SWD-63S50W Number: 12SWNW

Qtrqr: SWN Sec: 12 Twp: 3S Range: 50W Meridian: 6

Latitude: 39.810680 Longitude: -102.930559

CORRECTIVE ACTIONS:

2 CA# 170256

Corrective Action: Properly dispose of oily waste in accordance with 905.e.

Date: 05/12/2023

Response: CA COMPLETED

Date of Completion: 05/03/2023

Operator Comment: wellhead area cleaned

COGCC Decision: _____

COGCC
Representative: _____

3 CA# 170257

Corrective Action: Perform reclamation in accordance with Rule 1003. Corrective action date is the date the location was observed out of compliance.

Date: 04/20/2023

Response: CA COMPLETED

Date of Completion: 05/02/2023

Operator
Comment:

The photos associated with this inspection misrepresent the fact that this is an access road to the well that Impetro has permanent and unabridged access to per our surface use agreement. The road to this location (See attached screenshot from Google Earth) is not as well defined as our access roads in the non-crop sections of our lease out of respect to the landowner during growing season. Foot travel is predominantly used during the growing season to make site inspections. Nevertheless, Impetro can access this location whenever needed via this road by vehicles, as needed.

Pursuant to 1003.b. All disturbed areas affected by drilling or subsequent operations, except areas reasonably needed for production operations to be commenced within twelve (12) months; Impetro just conducted a workover of this well on 4/17/2023 and this inspection took place on 4/20/2023. Impetro is working with the landowner to reestablish areas surrounding the well that are not needed for production and maintenance of the well; if over the course of the growing season the crops still appear to be under grown/ damaged we will work with the landowner to reclaim areas that need to be addressed.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Brent Bongers

Signed: _____

Title: President/COO

Date: 5/3/2023 11:36:15 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403391963	Aerial of Access
403392479	12-12 wellhead
403392480	Ground View of Access

Total Attach: 3 Files