

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403373612

Date Received:

04/14/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 3 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Romana Cowden

Phone

720-951-5895

Email

COGCC.inspections@caerusoilandgas.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696204788

Inspection Date: 03/21/2023

FIR Submit Date: 03/23/2023

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335780

Location Name: CHEVRON-66S96W Number: 17SESW County: _____

Qtrqr: SESW Sec: 17 Twp: 6S Range: 96W Meridian: 6

Latitude: 39.519810 Longitude: -108.133310

FACILITY - API Number: 05-045- -00 Facility ID: 335780

Facility Name: CHEVRON-66S96W Number: 17SESW

Qtrqr: SESW Sec: 17 Twp: 6S Range: 96W Meridian: 6

Latitude: 39.519810 Longitude: -108.133310

CORRECTIVE ACTIONS:

2 CA# 168479

Corrective Action: Areas of erosion/degradation due to runoff from the working pad, onto the interim slopes of the Location, require repairing, stabilization and reclamation as necessary to meet 1003 standards.

Date: 04/30/2023

Response: CA COMPLETED

Date of Completion: 04/03/2023

Operator Comment: Stormwater BMPs were repaired, location was graded, and gravel was re-distributed. We have tracking control BMPS in place right before accessing paved County Road 215. These tracking controls support all pads in the Garden Gulch area, and are regularly maintained. See attached photo and map of tracking control BMPS.

COGCC Decision: Not Approved

COGCC
Representative:

COGCC Decision "not approved".

Corrective action is regarding erosion degradation due to runoff from the working pad, onto the interim slopes of the Location. Operator comments/documentation appear to be directed at stormwater management on the working pad surface; Operator has provided no documentation or details regarding repairing, stabilization and reclamation of the interim areas degraded due to runoff per the CA.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed:

Title: EHS

Date: 4/14/2023 6:38:57 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403373612	FIR RESOLUTION SUBMITTED
403373613	Map of tracking BMPS
403373614	Regraded

Total Attach: 3 Files