

TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1SESE

Location #334948



SW Corner of Location – Photo #03544



SE Corner of Location – Photo #03545

TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1SESE

Location #334948



NE Corner of Location – Photo #03546



NW Corner of Location – Photo #03547

TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1SESE

Location #334948



Wellheads – Photo #03548



Separators – Photo #03553



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1SESE

Location #334948



Tank Battery – Photo #03554



Open-Ended Load Line – Photo #03557

TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1SESE

Location #334948



Rill Erosion Transporting Sediment Across Lease Road – Photo #03558



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #03559