

# TEP ROCKY MOUNTAIN LLC, BARRETT-66S96W/36SWSW

Location #324096



NE Corner of Location – Photo #03600



SE Corner of Location – Photo #03601



# TEP ROCKY MOUNTAIN LLC, BARRETT-66S96W/36SWSW

## Location #324096



SW Corner of Location – Photo #03602



NW Corner of Location – Photo #03603



# TEP ROCKY MOUNTAIN LLC, BARRETT-66S96W/36SWSW

Location #324096



Wellhead – Photo #03605



Lack of Stabilization/Degradation Causing Transportation of Sediment – Photo #03604



# TEP ROCKY MOUNTAIN LLC, BARRETT-66S96W/36SWSW

Location #324096



**Location Lacks Stabilization – Photo #03607**



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #03608**