

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/19/2023

Submitted Date:

05/22/2023

Document Number:

708300454

FIELD INSPECTION FORMLoc ID 324096 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|-------|------------------------------------|---------|
| Kellerby, Shaun | | shaun.kellerby@state.co.us | |
| , TEP | | COGCCInspectionReports@terraep.com | |

General Comment:**COGCC Inspection Report Summary**

On 5/19/2023 at approximately 10:30, Compliance Inspector Matthew Morris conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC, BARRETT-66S96W/36SWSW at Location ID #324096 in Garfield County, Colorado.

During the inspection, the following compliance issues were observed:

1) Stormwater; refer to Stormwater section

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, and/or Wildlife Management area.

LocationOverall Good: ☐

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 911/(970) 285-9377

Corrective Action:

Date: _____

Overall Good: ☐

| | | | | | |
|----------------|------|--------|--|--|--|
| Spills: | | | | | |
| Type | Area | Volume | | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|--|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Bradenhead | # 1 | | |
| Comment: | No form of pressure monitoring equipment located on Bradenheads. All Bradenhead valves are accessible. | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|------------------------------------|
| | | Ditches | | | | |
| | | Sediment Traps | | | | |
| | | Berms | | | | |
| Berms | | | | | | |
| Compaction | Fail | | | | | Location lacks stabilization |
| Other | Fail | | | | | Insufficient vehicle tracking BMPs |
| | | Gravel | | | | |
| | | Rip Rap | | | | |
| | | Culverts | | | | |
| Ditches | | | | | | |

Comment: 1) Location lacks stabilization with insufficient vehicle tracking BMPs in place to minimize transportation of sediment.
 2) Site degradation from plow causing transport of sediment and lack of stabilization.

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to comply with Rule 1002.

Date: 06/06/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 708300455 | Photo Log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6120933 |