

Interim Reclamation and Stormwater Inspection

Date: 05/26/2023

Operator: WHITING OIL & GAS CORPORATION -
96155

Location ID: 435421

Inspection Document #: 708200313

Weld County, CO

NESW Section 26 T10N R58W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Razor 26 Production
Location ID: 435421



Photo 1. Western interim areas. During this inspection, Staff observed that the western interim areas do not appear to be progressing towards Rule 1003 standards as areas of non-uniform vegetation cover were evidenced by bare soil. Additional reclamation activities are required to meet Rule 1003 standards.

Inspection Photos
Location Name: Razor 26 Production
Location ID: 435421



Photo 2. See comments in Photo 1.

Inspection Photos
Location Name: Razor 26 Production
Location ID: 435421



Photo 3. See comments in Photo 1.

Inspection Photos
Location Name: Razor 26 Production
Location ID: 435421



Photo 4. Northern portion of production area. Apparent impacted material being stored on the north end of the location, possibly associated with Remediation Project #29364, was not placed on a impervious liner and sediment control logs appeared inadequate with evidence of sediment transport outside of BMPs. More robust BMPs will need to be implemented to prevent impacted material from migrating outside of containment.

Inspection Photos
Location Name: Razor 26 Production
Location ID: 435421



Photo 5. See comments in Photo 4.

Inspection Photos
Location Name: Razor 26 Production
Location ID: 435421



Photo 6. Perimeter fencing around open excavation associated with Remediation Project #29346 appears inadequate to exclude wildlife entry.

Inspection Photos
Location Name: Razor 26 Production
Location ID: 435421



Photo 7. Stained soil observed on the southern end of the location, south of compressors, will need to be properly disposed of in accordance with 905.e.

Inspection Photos
Location Name: Razor 26 Production
Location ID: 435421



Photo 8. Southeastern interim area. This portion of the interim areas appear to be progressing towards Rule 1003 standards with uniform vegetation cover of desirable species observed.