

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/04/2023

Submitted Date:

06/05/2023

Document Number:

700901466

**FIELD INSPECTION FORM**Loc ID 320305 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 41550

Name of Operator: TYLER ROCKIES EXPLORATION LTD

Address: P O BOX 119

City: TYLER State: TX Zip: 75710-

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Strawn, Mark		texcomo@sbcglobal.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203416	WELL	SI	07/01/2021	OW	001-08925	LINNEBUR 2-R	SI

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Rule 606: Weeds, dead weeds, trash, debris & unnecessary / unused equipment.		
Corrective Action:	Within a designated setback, remove trash, debris and weeds per Rule 606. Corrective Action Date 6/30/2023 days. See attached photo # 2,4,5 & 6.		Date: 06/30/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Pump Jack	# 1		corrective date
Comment:	603.o.(3) Secondary containment is not sufficiently impervious to contain spilled or released materials.		
Corrective Action:	secondary containment for chemicals, Corrective Action Date 7/7/2023 to remove stained soil. See attached photo # 6.		Date: 07/07/2023
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		39.746735,-104.031022
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Rule 906: Stained soil around load out line . Control and contain spills/releases and clean up per Rule 906.				
Corrective Action:	Control and contain spills/releases and clean up per Rule 906. Corrective Action Date 7/7/2023 to remove stained soil. See attached photo # 2				Date: 07/07/2023

**Wells Served By Facilities Above****AirsID**

API Number

API Number

AirsID

001-08925

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 203416 Type: WELL API Number: 001-08925 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 12/12/2022 Annual Brhd Completed? \_\_\_\_\_

Last Brhd Test Results Initial Surf Csg Pressure: 10 Fluid Type: WATER H2O

End Surf Csg Pressure: 0

Comment: Apeared to be plumbed to surface

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary  On Thursday May 4th 2023 at approximately 10:45am. I, Inspector Chane Finkenbinder, conducted an on-site inspection.  Operator: TYLER ROCKIES EXPLORADTION  Location name: LINNEBUR 2-R  API # 001-08925  Location ID #: 320305  County: Adams  While there, I observed a shut in well.  During this inspection the following possible compliance issues were observed:  Rule 606: Weeds, dead weeds, trash, debris &amp; unnecessary / unused equipment. Within a designated setback, remove trash, debris and weeds per Rule 606. Corrective Action Date 6/30/2023 days. See attached photo # 2,4,5 &amp; 6.  Rule 906: Stained soil around. Control and contain spills/releases and clean up per Rule 906. Corrective Action Date 7/7/2023 to remove stained soil. See attached photo # 2  603.o.(3) Secondary containment is not sufficiently impervious to contain spilled or released materials. secondary contanment on chemicals, Corrective Action Date 7/7/2023. See attached photo # 6.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.  This is a summary of inspection report.</p>	finkenbc	06/05/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
700901467	Inspection photos	<a href="http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6137605">http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6137605</a>