

Replug By Other Operator

Document Number:
403425715

Date Received:

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 22111 Contact Name: Richard Murray

Name of Operator: D & B VENTURES Phone: (970) 989-3092

Address: _____ Fax: _____

City: DENVER State: CO Zip: _____ Email: g.richard.murray@state.co.us

For "Intent" 24 hour notice required, Name: _____ Tel: _____

COGCC contact: Email: _____

Type of Well Abandonment Report: Notice of Intent to Abandon Subsequent Report of Abandonment

API Number 05-067-05236-00

Well Name: FERGUSON (OWP) Well Number: 1

Location: QtrQtr: SWNW Section: 34 Township: 33N Range: 12W Meridian: N

County: LA PLATA Federal, Indian or State Lease Number: _____

Field Name: RED MESA Field Number: 72890

Only Complete the Following Background Information for Intent to Abandon

Latitude: 37.062899 Longitude: -108.144811

GPS Data: GPS Quality Value: 0.5 Type of GPS Quality Value: Accuracy in Meters Date of Measurement: 05/31/2023

Reason for Abandonment: Dry Production Sub-economic Mechanical Problems

Other _____

Casing to be pulled: Yes No Estimated Depth: _____

Fish in Hole: Yes No If yes, explain details below

Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below

Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
SANASTEE	2705	2796	11/03/1962	B PLUG CEMENT TOP	2705
Total: 1 zone(s)					

Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+0/1	10+3/4	UK	32	0	57	25	57	0	VISU
1ST	7+0/1	5+0/1	UK	11.5	0	2705	75	2705	2045	CALC

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged:

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Number of Days from Setting Surface Plug
Surface Plug Setting Date: 11/16/1972 Cut and Cap Date: 06/02/2023 to Capping or Sealing the Well: 1846
0

*Wireline Contractor: No wireline performed *Cementing Contractor: No cement placed

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1105 Yes No

Technical Detail/Comments:

This well is in the Orphan Well Program,

D & B Ventures Ferguson #1 API 05-067-05236.

Well was plugged 11/16/1962 Plugging Record Doc #00677394 and 2/7/1963 Completion Report Doc #0677395. Methane assessment and Soil Gas Survey were performed by Cottonwood Consulting. Both came back negative. No Bradenhead test was performed due to no Bradenhead. Well has cement to surface in Surface Casing and 2-3/8" tubing. The tubing was used to place cement in well and was left in place. Surface casing set to 57' then open hole to 1,500'. Cottonwood, COGCC OWP and COGCC Engineering recommended to cut, cap and bury well. Well was cut 4' below grade and well marker plate welded on.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Richard Murray

Title: OWP Specialist Date: _____ Email: g.richard.murray@gmail.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY:

<u>COA Type</u>	<u>Description</u>
0 COA	

Attachment List

<u>Att Doc Num</u>	<u>Name</u>
403428429	WELLBORE DIAGRAM

Total Attach: 1 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)