

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/04/2023

Submitted Date:

06/05/2023

Document Number:

700901466

**FIELD INSPECTION FORM**

Loc ID 320305 Inspector Name: Finkenbinder, Chane On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 41550  
Name of Operator: TYLER ROCKIES EXPLORATION LTD  
Address: P O BOX 119  
City: TYLER State: TX Zip: 75710-

**Findings:**

- 7 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Strawn, Mark		texcomo@sbcglobal.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203416	WELL	SI	07/01/2021	OW	001-08925	LINNEBUR 2-R	SI

**General Comment:**

**Location**

Overall Good:

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Rule 606: Weeds, dead weeds, trash, debris & unnecessary / unused equipment.		
Corrective Action:	Within a designated setback, remove trash, debris and weeds per Rule 606. Corrective Action Date 6/30/2023 days. See attached photo # 2,4,5 & 6.		Date: 06/30/2023

Overall Good:

**Spills:**

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#	corrective date
Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:
Vertical Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:
Pump Jack	# 1	
Comment:	603.o.(3) Secondary containment is not sufficiently impervious to contain spilled or released materials.	
Corrective Action:	secondary containment for chemicals, Corrective Action Date 7/7/2023 to remove stained soil. See attached photo # 6.	
		Date: 07/07/2023

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		39.746735,-104.031022
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berm				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Rule 906: Stained soil around load out line . Control and contain spills/releases and clean up per Rule 906.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906. Corrective Action Date 7/7/2023 to remove stained soil. See attached photo # 2			Date: 07/07/2023

**Wells Served By Facilities Above**

**AirsID**

API Number
001-08925

API Number	AirsID
------------	--------

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 203416 Type: WELL API Number: 001-08925 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 12/12/2022 Annual Brhd Completed? \_\_\_\_\_

Last Brhd Test Results Initial Surf Csg Pressure: 10 Fluid Type: WATER H2O

End Surf Csg Pressure: 0

Comment: Apeared to be plumbed to surface

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a>                      On Thursday May 4th 2023 at approximately 10:45am. I, Inspector Chane Finkenbinder, conducted an on-site inspection.                      Operator: TYLER ROCKIES EXPLORADTION                      Location name: LINNEBUR 2-R                      API # 001-08925                      Location ID #: 320305                      County: Adams                      While there, I observed a shut in well.                      During this inspection the following possible compliance issues were observed:                      Rule 606: Weeds, dead weeds, trash, debris &amp; unnecessary / unused equipment. Within a designated setback, remove trash, debris and weeds per Rule 606. Corrective Action Date 6/30/2023 days. See attached photo # 2,4,5 &amp; 6.                      Rule 906: Stained soil around. Control and contain spills/releases and clean up per Rule 906. Corrective Action Date 7/7/2023 to remove stained soil. See attached photo # 2                      603.o.(3) Secondary containment is not sufficiently impervious to contain spilled or released materials. secondary contanment on chemicals, Corrective Action Date 7/7/2023. See attached photo # 6.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	finkenbc	06/05/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403425050	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6137609">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6137609</a>
700901467	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6137605">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6137605</a>