

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/01/2023

Submitted Date:

06/06/2023

Document Number:

709400214

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
 \_\_\_\_\_ WOLD, REED \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☒ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		cogcc@kpk.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
482821	TANK BATTERY	AC	09/08/2022		-	Koch Tank Battery	AC
483852	SPILL OR RELEASE	CL			-	Koch Tank Battery Separator	

**General Comment:**

This is an interim and stormwater inspection.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	DEBRIS		
Comment:	Fill slope berm is constructed of crushed concrete a prohibited material, increasing the pH of stormwater runoff.		
Corrective Action:	Comply with rule 606.d. remove debris and building material rubbish (crushed concrete).		Date: 06/01/2023
Type	WEEDS		
Comment:	Failure to control and manage weeds to prevent weed waste and prevent the spread of seeds onto adjacent lands.		
Corrective Action:	Comply with Rule 606.c.		Date: 06/01/2023
Type	OTHER		
Comment:	No berm was present around open excavation allowing stormwater to flow in.		
Corrective Action:	Operator shall install BMPs in accordance with 1002.f.(2) to prevent erosion, run-on/off into the open excavation and off location.		Date: 06/01/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Excavation exclusionary fence is torn, falling down and inadequate for preventive safety measures.		
Corrective Action:	Operator shall repair and maintain best management practices to control and contain all spills/releases of E&P waste to protect the environment, public health, safety and welfare and the environment as required by rule 913.b(5)B.i which requires that Operators will fence or cover open remediation excavations to prevent access when sites are not attended. The site was not attended at the time of the inspection.		Date: 06/01/2023

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities								
Facility ID:	482821	Type:	TANK	API Number: -	Status:	AC	Insp. Status:	AC
Facility ID:	483852	Type:	SPILL OR	API Number: -	Status:	CL	Insp. Status:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Fail					Concrete in fill slope berm

Comment: [Inadequate BMP on fill slope berm, stormwater is allowed to runoff location on the Northeast side unfiltered in to the vegetation off site.](#)

Corrective Action: [Comply with rule 1002.f.](#)

Date: 06/01/2023

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">Per Rule 1002.f., oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004. Operators shall employ BMPs, as necessary to comply with this rule, at all oil and gas locations, including, but not limited to, well pads, soil stock piles, access roads, tank batteries, compressor stations, and pipeline rights of way. BMPs shall be selected based on site specific conditions, such as slope, vegetation cover, and proximity to water bodies, and may include maintaining in-place some or all of the BMPs installed during the construction phase of the facility. Where applicable based on site-specific conditions, operators shall implement BMPs in accordance with good engineering practices.</a>	woldr	06/06/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403424679	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6137280">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6137280</a>
709400217	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6136698">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6136698</a>