

TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1SESE

Location #334948

Date: 6/19/2023



SW Corner of Location – Photo #04595



NW Corner of Location – Photo #04596

TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1SESE

Location #334948

Date: 6/19/2023



NE Corner of Location – Photo #04597



SE Corner of Location – Photo #04598

TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1SESE

Location #334948

Date: 6/19/2023



Wellheads – Photo #04599



Separators – Photo #04600



TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1SESE

Location #334948

Date: 6/19/2023



Tank Battery – Photo #04601



Rill Erosion/Ditch Full of Sediment/Needs Maintenance – Photo #04604

TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1SESE

Location #334948

Date: 6/19/2023



Rill Erosion/Check Dam Needs Maintenance – Photo #04605



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #04603