

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/29/2023

Submitted Date:

06/30/2023

Document Number:

690204389

FIELD INSPECTION FORM

Loc ID 324831 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
5 Number of Comments
4 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 83130
 Name of Operator: STRACHAN EXPLORATION INC
 Address: 383 INVERNESS PKWY, STE 360
 City: ENGLEWOOD State: CO Zip: 80112

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
HARMS JASON		jason@strachanexploration.com	
BEAR STACY		stacy@strachanexploration.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213004	WELL	PR	06/01/2022	OW	061-06365	FRAZEE 2-6	RI

General Comment:
 On 6/29/2023, Ryan Costa conducted a location inspection. See attached photos and additional details within this report.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	The labeling on the tanks is faded and/or missing. Corrective action is the day of inspection and the location will remain out of compliance until completed.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	06/29/2023

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

Overall Good:

Spills:

Type	Area	Volume		
Crude Oil	Pump Jack			
Comment:	There is oily sludge that has spilled onto the ground that needs to be cleaned up. Operator was notified the day of inspection for immediate clean up.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date:	06/29/2023

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	TANK BATTERY		
Comment:	The fence around the tanks and production equipment is inadequate to prevent livestock entry. Corrective action is the day of inspection and the location will remain out of compliance until completed.		
Corrective Action:	Comply with the fencing requirements per the 1002a rules		Date: 06/29/2023

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	2		STEEL AST		
Comment:	<input type="text"/>				
Corrective Action:	<input type="text"/>				Date: <input type="text"/>

Paint

Condition	<input type="text"/>				
Other (Content)	<input type="text"/>				
Other (Capacity)	<input type="text"/>				
Other (Type)	<input type="text"/>				

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	There are two large volume tanks with no labeling and no secondary containment. Corrective action is the day of inspection and the location will remain out of compliance until completed.			

Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.	Date:	06/29/2023
--------------------	--	-------	------------

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403451282	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6166836
690204390	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6166820