

Inspection Photos

7/10/2023

Operator: GUNNISON ENERGY LLC - 10515

Location Number: 427218

Gunnison County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location Number: 427218



Photo 1: Photos 1-2 taken from the east end of the Location. Photos provide an overview of the Location from southeast, south, southwest to west. Photos show interim reclamation of areas not needed for production have not been conducted in accordance with Rule 1003.b.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location Number: 427218



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location Number: 427218



Photo 3: Photos 3-4 taken from the southeast end of the Location. Photos provide an overview of the Location from southwest, west north to northeast. Photos show interim reclamation of areas not needed for production have not been conducted in accordance with Rule 1003.b.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location Number: 427218



Photo 4: See comments under photo 3.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources



Photo 5: 2019 Google Earth aerial image of the Location. Polygon represents approximate working pad areas of the Location not reasonably needed for production requiring work including, but not limited to, compaction alleviation, recontouring/regrading and reclamation.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location Number: 427218



Photo 6: Photos show tanks at the battery facility missing required information, such as Operator name and emergency contact number.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location Number: 427218



Photo 7: Photos examples showing holes/tears observed within the liner of the tank battery facility's secondary containment BMPs.

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location Number: 427218



Photo 4: Photos show trash debris improperly stored within the secondary containment of the tank battery facility.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location Number: 427218



Photo 9: Photo taken from the culvert outlet on the north end of the Location. Photo shows BMPs remain missing or insufficient per good engineering practices at the outlet. Erosion degradation remains apparent. Operator appears to have only dumped river-rock mixed with sediment into the gully formation.