



FORM
6
Rev
11/20

State of Colorado
Oil and Gas Conservation Commission
1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DEETOEES

Replug By Other Operator

Document Number:
403461667

Date Received:

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number:10651Contact Name:Alex Waner

Name of Operator:VERDAD RESOURCES LLCPhone:(303) 2049636

Address:1125 17TH STREET SUITE 550Fax:

City:DENVERState:COZip:80202Email:awaner@verdadresources.com

For "Intent" 24 hour notice required,Name:Tel:

COGCC contact:Email:

Type of Well Abandonment Report:☐ Notice of Intent to Abandon☒ Subsequent Report of Abandonment

API Number05-123-07906-00

Well Name:BUCHERWell Number:1

Location:QtrQtr:NWNWSection:1Township:9NRange:59WMeridian:6

County:WELDFederal, Indian or State Lease Number:

Field Name:IGOCREEKField Number:38310

Only Complete the Following Background Information for Intent to Abandon

Latitude:40.785279Longitude:-103.933837

GPS Data:GPS Quality Value:1.3Type of GPS Quality Value:Date of Measurement:04/28/2023

Reason for Abandonment:☐ Dry☐ Production Sub-economic☐ Mechanical Problems

☐ Other

Casing to be pulled:☐ Yes☐ NoEstimated Depth:

Fish in Hole:☐ Yes☐ NoIf yes, explain details below

Wellbore has Uncemented Casing leaks:☐ Yes☐ NoIf yes, explain details below

Details:

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
J SAND	6866	6874	10/16/1974	SAND PLUG	

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8		23	0	138	100	138	0	VISU
1ST	7+7/8	5+1/2		15.5	5723	6938	150	6938	6032	CALC

Date Run: 7/12/2023 Doc [#403461667] Well Name: BUCHER 1

Page 1 of 3

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set	135	sks cmt from	5684	ft. to	5330	ft.	Plug Type:	OPEN HOLE	Plug Tagged:	<input checked="" type="checkbox"/>
Set	60	sks cmt from	2514	ft. to	2397	ft.	Plug Type:	OPEN HOLE	Plug Tagged:	<input checked="" type="checkbox"/>
Set	135	sks cmt from	1656	ft. to	1115	ft.	Plug Type:	OPEN HOLE	Plug Tagged:	<input checked="" type="checkbox"/>
Set	150	sks cmt from	606	ft. to	377	ft.	Plug Type:	OPEN HOLE	Plug Tagged:	<input checked="" type="checkbox"/>
Set	_____	sks cmt from	_____	ft. to	_____	ft.	Plug Type:	_____	Plug Tagged:	<input type="checkbox"/>

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 275 sacks half in. half out surface casing from 377 ft. to 232 ft. Plug Tagged: ☒

Set 68 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing

Surface Plug Setting Date: 06/19/2023 Cut and Cap Date: 06/26/2023 Number of Days from Setting Surface Plug to Capping or Sealing the Well: 7

*Wireline Contractor: _____

*Cementing Contractor: Bohler Well Services

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____

Print Name: Alex Waner

Title: Ops Engineer

Date: _____

Email: awaner@verdadresouces.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____

Date: _____

CONDITIONS OF APPROVAL, IF ANY:

COA Type

Description

0 COA	
-------	--

Attachment List

<u>Att Doc Num</u>	<u>Name</u>
403461676	WELLBORE DIAGRAM
403461679	LOCATION PHOTO
403461687	CEMENT JOB SUMMARY
403461688	CEMENT JOB SUMMARY

Total Attach: 4 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)