

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403458187

Date Received:
07/10/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 88370

Name of Operator: TIMKA RESOURCES LTD

Address: 2077 BAYFRONT DR

City: WINDSOR State: CO Zip: 80550

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Pivonka, Todd</u>	<u>(970) 667-9861</u>	<u>timkaresources@hotmail.com</u>
<u>Heibel, Krystal</u>		<u>krystal.heibel@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 708200338

Inspection Date: 06/16/2023

FIR Submit Date: 06/22/2023

FIR Status: _____

Inspected Operator Information:

Company Name: TIMKA RESOURCES LTD

Company Number: 88370

Address: 2077 BAYFRONT DR

City: WINDSOR State: CO Zip: 80550

LOCATION - Location ID: 312278

Location Name: BARNHART ET AL-68N55W Number: 29NENE County: _____

Qtrqtr: NENE Sec: 29 Twp: 8N Range: 55W Meridian: 6

Latitude: 40.638360 Longitude: -103.545080

FACILITY - API Number: 05-075- -00 Facility ID: 312278

Facility Name: BARNHART ET AL-68N55W Number: 29NENE

Qtrqtr: NENE Sec: 29 Twp: 8N Range: 55W Meridian: 6

Latitude: 40.638360 Longitude: -103.545080

CORRECTIVE ACTIONS:

1 CA# 173583

Corrective Action: Properly dispose of oily waste in accordance with 905.e. Corrective action date is the date the location was observed out of compliance.

Date: 06/16/2023

Response: CA COMPLETED

Date of Completion: 07/07/2023

Operator Comment: Stained soil noted in the inspection report was over-excavated and transported to Pawnee Waste for disposal. Approximately 3 tons (2 cubic yards) of soil was removed and no staining was observed subsequent to removal. During the initial facility closure, no stained soils were observed. The origin of the stained soil observed during the inspection is unknown and is assumed to be caused by others not related to the facility operation and/or closure activities. Please refer to the attached soil disposal manifest.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

2 CA# 173584

Corrective Action: Comply with Rule 1004. Corrective action date is the date the location was observed out of compliance.

Date: 06/16/2023

Response: CA COMPLETED

Date of Completion: 07/07/2023

Operator Comment: All surface equipment, pipe corners, t-posts, other debris, and undesirable weeds noted in the inspection have been removed and mitigated. Please refer to the attached site photographic log.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

3 CA# 173585

Corrective Action: Comply with Rule 1002.f. Implement or modify BMPs for improved material handling and spill prevention and Install or repair required BMPs. Corrective action date is the date the location was observed out of compliance.

Date: 06/16/2023

Response: CA COMPLETED

Date of Completion: 07/07/2023

Operator Comment: Stormwater controls and BMPs have been installed during the interim Form 27-Supplemental report and reclamation plan review. The soil pile noted in the inspection was sampled previously and laboratory analytical results were below the Table 915-1 regulatory standards. The soil is anticipated to be used as backfill subsequent to approval of the Form 27-Supplemental report and associated reclamation plan. Please refer to attached photographic log for installed BMPs.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective actions have been completed as described herein. Please refer to the attached waste disposal manifest and photographic log. A Form 27-Supplemental report and associated Reclamation Plan will be submitted for regulatory review and approval prior to site closure.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Drezden Kinnaird

Signed: _____

Title: Consultant

Date: 7/10/2023 12:10:27 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403458187	FIR RESOLUTION SUBMITTED
403458237	Waste disposal manifest
403458271	FIRR Photographic Log

Total Attach: 3 Files