

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/13/2023

Submitted Date:

07/13/2023

Document Number:

702501639**FIELD INSPECTION FORM**Loc ID 314355 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10556Name of Operator: PLUG NICKEL OIL COMPANY INCAddress: PO BOX 1937City: VERNAL State: UT Zip: 84078**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hogue, Jimmy	(435) 828-7666	hogue@stratanet.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228535	WELL	PR	04/01/2023	OW	103-05424	HUSKY 20	PR

General Comment:**COGCC Inspection Report Summary**

On Wednesday, 7/13/23, Inspector Kirby Burchett, conducted a follow up field inspection at Plug Nickel Oil Co. on the Husky 20 well, Location #314355, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Inspection #702501113 on 4/7/23. All Corrective Actions have been resolved.

While there during normal operations the following compliance issues were observed:

1. Oily rags.
2. Open valve on loadline.
3. Gearbox leak on pumping unit.

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 435-828-7666 or 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Oily rags on tank landing		
Corrective Action:	Combustible materials such as oily rags and waste will be stored in covered metal containers.	Date:	07/21/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
Lube Oil	Pump Jack	<= 1 bbl		
Comment:	Oily waste from leak on pumping unit			
Corrective Action:	Repair leak. Remove and properly dispose of oily waste and impacted soil.			Date: 07/29/2023

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Deadman # & Marked	# 4		corrective date
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	200 BBLS	STEEL AST		,

Comment:	Loadline and tank valves capped or plugged. Secondary valve on loadline left open.	
Corrective Action:	All loadlines or tank valves that can be used as a loadline will be capped or plugged.	Date: 07/19/2023

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate				
Comment:	Unlined				
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	228535	Type:	WELL	API Number:	103-05424	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Last production - April 2023								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Berms						

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403464254	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6180839
702501644	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6180837