

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/24/2023

Submitted Date:

07/26/2023

Document Number:

690204456**FIELD INSPECTION FORM**Loc ID 307267 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1875 LAWRENCE ST STE 1150City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, Evergreen		cogcc.evergreen@enrllc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217324	WELL	SI	01/01/2022	CBM	071-06100	HORN SPRING GAS COM 1-32-33	RI

**General Comment:**

On 7/24/2023, Ryan Costa conducted a location and stormwater management inspection.  
See attached photos and additional details within this report.

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		Date: _____
Corrective Action:		

**Good Housekeeping:**

Type	OTHER		
Comment:	There is oily fluid in the engine skid that needs to be cleaned up. Corrective action will remain out of compliance until completed.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes.		Date: 07/24/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment:		There is erosion at the access road which is transporting sediment towards the County Road. The cattleguard at the beginning of the access road has filled in with sediment. Corrective action will remain out of compliance until completed.				
Corrective Action:		Install or repair required BMPs per Rule 1002.f.(2)				Date: 07/24/2023
<b>Pits:</b> <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690204457	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6195653">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6195653</a>