

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 24-27 Pad
Location ID: 335197



**Location Overview: Location is within High Priority/Density
Habitat areas & Bald Eagle Nest/Roost Sites & in close
proximity to NSO Habitat.**

Section/Township/Range: 27 6S94W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 24-27 Pad
Location ID: 335197



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 24-27 Pad
Location ID: 335197



Photo # 5913 From Inspection 708900316 conducted on 04/20/2023 Erosion & Transport of sediment/Sediment encroaching on equipment

Photo # 4645 Erosion & Transport of sediment/Sediment encroaching on equipment

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 24-27 Pad
Location ID: 335197



Photo # 5914 From Inspection 708900316 conducted on 04/20/2023 Erosion & Transport of sediment/Sediment encroaching on equipment

Photo # 4635 Erosion & Transport of sediment/Sediment encroaching on equipment

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 24-27 Pad
Location ID: 335197



Photo # 5915 From Inspection 708900316 conducted on 04/20/2023 Erosion & Transport of sediment/Sediment encroaching on equipment



Photo # 4638 Erosion & Transport of sediment/Sediment encroaching on equipment

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 24-27 Pad
Location ID: 335197



Photo # 5922 From Inspection 708900316 conducted on 04/20/2023 Erosion & Transport of sediment/Sediment encroaching on equipment

Photo # 4633 Erosion & Transport of sediment/Sediment encroaching on equipment

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 24-27 Pad
Location ID: 335197



Photo # 4641 Erosion & Transport of sediment/Sediment encroaching on equipment

Photo # 4642 Erosion & Transport of sediment/Sediment encroaching on equipment

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 24-27 Pad
Location ID: 335197



Photo # 4647 Erosion & Transport of sediment/Sediment encroaching on equipment



Photo # 4656 Erosion & Transport of sediment/Sediment encroaching on equipment