

FORM

6

Rev
11/20

State of Colorado

Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Replug By Other Operator

Document Number:

403492835

Date Received:

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 10651

Contact Name: Alex Waner

Name of Operator: VERDAD RESOURCES LLC

Phone: (303) 2049636

Address: 1125 17TH STREET SUITE 550

Fax:

City: DENVER

State: CO

Zip: 80202

Email: awaner@veradresources.com

For "Intent" 24 hour notice required,

Name:

Tel:

COGCC contact:

Email:

Type of Well Abandonment Report: ☐ Notice of Intent to Abandon ☒ Subsequent Report of Abandonment

API Number 05-123-05728-00

Well Name: MCCLEMENT

Well Number: 1

Location: QtrQtr: SENE

Section: 2

Township: 9N

Range: 59W

Meridian: 6

County: WELD

Federal, Indian or State Lease Number:

Field Name: WILDCAT

Field Number: 99999

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.781873

Longitude: -103.938373

GPS Data: GPS Quality Value: 1.5 Type of GPS Quality Value: Date of Measurement: 07/10/2023

Reason for Abandonment: ☐ Dry ☐ Production Sub-economic ☐ Mechanical Problems☐ OtherCasing to be pulled: ☐ Yes☐ No

Estimated Depth:

Fish in Hole: ☐ Yes☐ No

If yes, explain details below

Wellbore has Uncemented Casing leaks: ☐ Yes☐ No

If yes, explain details below

Details:

Current and Previously Abandoned Zones

Formation

Perf. Top

Perf. Btm

Abandoned Date

Method of Isolation

Plug Depth

Total: 0 zone(s)

Casing History

| Casing Type | Size of Hole | Size of Casing | Grade | Wt/Ft | Csg/Liner Top | Setting Depth | Sacks Cmt | Cmt Btm | Cmt Top | Status |
|-------------|--------------|----------------|-------|-------|---------------|---------------|-----------|---------|---------|--------|
| SURF | 12+1/4 | 8+5/8 | | 22 | 0 | 247 | 175 | 247 | 0 | VISU |

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

| | | | | | | | | | | |
|-----|-----|--------------|------|--------|------|-----|------------|-----------|--------------|-------------------------------------|
| Set | 90 | sks cmt from | 6838 | ft. to | 6535 | ft. | Plug Type: | OPEN HOLE | Plug Tagged: | <input checked="" type="checkbox"/> |
| Set | 175 | sks cmt from | 6112 | ft. to | 5700 | ft. | Plug Type: | OPEN HOLE | Plug Tagged: | <input type="checkbox"/> |
| Set | 65 | sks cmt from | 2514 | ft. to | 2312 | ft. | Plug Type: | OPEN HOLE | Plug Tagged: | <input checked="" type="checkbox"/> |
| Set | 135 | sks cmt from | 1814 | ft. to | 1369 | ft. | Plug Type: | OPEN HOLE | Plug Tagged: | <input checked="" type="checkbox"/> |
| Set | 125 | sks cmt from | 668 | ft. to | 545 | ft. | Plug Type: | OPEN HOLE | Plug Tagged: | <input checked="" type="checkbox"/> |

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 200 sacks half in. half out surface casing from 544 ft. to 268 ft. Plug Tagged: ☒

Set 120 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing

Surface Plug Setting Date: 08/03/2023 Cut and Cap Date: 08/09/2023 Number of Days from Setting Surface Plug to Capping or Sealing the Well: 6

*Wireline Contractor: n/a

*Cementing Contractor: Bohler Well Services

Type of Cement and Additives Used: Class G 15.8# 1.15 Yield

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____

Print Name: Alex Waner

Title: Operations Engineer

Date: _____

Email: awaner@verdadresources.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____

Date: _____

CONDITIONS OF APPROVAL, IF ANY:

COA Type

Description

| | |
|-------|--|
| 0 COA | |
|-------|--|

Attachment List

| <u>Att Doc Num</u> | <u>Name</u> |
|--------------------|--------------------|
| 403492850 | WELLBORE DIAGRAM |
| 403492854 | LOCATION PHOTO |
| 403492856 | LOCATION PHOTO |
| 403492857 | CEMENT JOB SUMMARY |
| 403492858 | CEMENT JOB SUMMARY |

Total Attach: 5 Files

General Comments

| <u>User Group</u> | <u>Comment</u> | <u>Comment Date</u> |
|-------------------|----------------|---------------------|
| | | Stamp Upon Approval |

Total: 0 comment(s)