

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/09/2023

Submitted Date:

08/09/2023

Document Number:

699107160

FIELD INSPECTION FORMLoc ID 331757 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 65110

Name of Operator: O'BRIEN ENERGY RESOURCES CORP

Address: 18 CONGRESS ST STE 207

City: PORTSMOUTH State: NH Zip: 03801

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Forma, Joseph	603-427-2099 x111	joeforma@obenergy.com	All Inspections
,		dnr_cogccengineering@state. co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265541	WELL	TA	07/29/2020	GW	123-21254	NORTH LOST CREEK 10	TA

General Comment:

Form 06A on file.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Adequate		
Corrective Action:		Date:	

Good Housekeeping:			
Type	WEEDS		
Comment:	Overgrown vegetation around the well needs to be removed for good housekeeping. See attached photos		
Corrective Action:	Comply with Rule 606.	Date:	09/22/2023

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	#		
Comment:	can not see due to overgrown vegetation		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 265541 Type: WELL API Number: 123-21254 Status: TA Insp. Status: TA

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: t/a

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 12/01/2021

Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: No updated annual BH test on file. Submit reports. Form 17 #403256994 indicates it was last tested on 12/9/20.

09/22/2023

Corrective Action: Submit reports as per Rule 207.

Date: _____

COGCC Comments

Comment

User

Date

ECMC Inspection Report Summary
 On Tuesday 8/8/23 at approximately 1030hrs I, Inspector Adam Burns,
 Conducted an on-site inspection at North Lost Creek 10 of O'Brien Energy Resources Corp.
 API #05-123-21254 in Weld County, Colorado.
 During this inspection the following possible compliance issues were observed:
 Overgrown vegetation around the well needs to be removed for good housekeeping.
 Comply with Rule 606. With a Corrective Action date of 9/22/23
 No updated annual BH test on file. Submit reports. Form 17 #403256994 indicates it was
 last tested on 12/9/20. Submit reports as per Rule 207. With a Corrective Action date of
 9/22/23
 A follow up on this site inspection needs to be conducted to ensure the
 compliance issues have been corrected to comply with ECMC rules.
 This is a summary of the inspection report.

burnsa

08/09/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403492024	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6213463
699107161	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6213445